



ASCENTAC  
**FiberClear**

# Optical Fiber Cleaning Wipes

## Ascentac CleMate 200

Perfect Wipe with No Cotton Batting & Efficient Cleaning of All Kinds of Stains

### Feature

- Dual use (Wet or Dry) and solvent resistant, not easy to damage
- Highly effective water absorption
- No lint, fluff or dust particles left
- Soft texture without damaging the surface of objects


### Application

- Electronic or precision instruments cleaning
- Fiber-optic connector end-face cleaning
- Medical equipment or lens wipe
- Printing equipment wipe

### Introduction

Ascentac FiberClear CleMate200 Series, Optical Fiber Cleaning Wipe, is lint-free and non-abrasive for cleaning laboratory & manufacturing facilities, fiber-optic connector end-face or other electronic items. The highly absorbent material is quite soft.


The series offers superior cleaning results without scratching connector end-face.



## Effectively Remove Contaminants



Alcohol residue



Dust



Finger print



After clean

## Specification

Optical Fiber Cleaning Wipe	
Model	CleMate210
Size (mm)	30 x 40
Package	500 pcs/box

## Ordering Information

**CleMate 02-002 XX**

Size & Package    
10 : 37 x 30 mm, 500 pcs/box

Example : CleMate 02-00210



© Copyright 2025 Ascentac. All rights reserved. The information in this document is subject to change without notice.

For the latest information regarding this product, please visit our website at <http://www.ascentac.com>



Contact us